



Схема однослойная вразвалку  
 $2p = 4, Z = 60, q = 2 \text{ и } 3, y = 1-16, 2-15, 3-14 \text{ и } 1-14, 2-13, a = 1.$




Схема полутораслойной концентрической обмотки  
 $2p = 4, Z = 60, a = 1$

